

MarcellusGas.Org

Document Disclaimer

The information contained in this document represents content obtained from the Pennsylvania Department of Environmental Protection. MarcellusGas.Org makes no claims whatsoever as to the accuracy, timeliness, or completeness of the information provided.

By downloading this document, you agree that you have accepted the terms and conditions set forth in the MarcellusGas.Org User Agreement located at:

http://www.marcellusgas.org/terms_of_use.php



Pennsylvania Department of Environmental Protection

321 North State Street
North Warren, PA 16365
October 30, 2008

Warren District Office

814-723-3273
Fax: 814-723-0964

CERTIFIED MAIL NO. [REDACTED]

[REDACTED]

Re: CID NO. 258396

[REDACTED]
Act 223 Section 208 Determination
Hamilton Township, McKean County


Dear [REDACTED]

The Department has investigated, in response to [REDACTED] September 15, 2008 complaint, the possible contamination of your water supply by nearby oil and gas activities.

After reviewing the results of your spring water analyses, aside from slightly elevated levels of iron (a secondary contaminant) observed in the September 15, 2008 sampling, all other parameters were within established drinking water standards. Another sample was taken on October 16, 2008, and the results from that sampling indicated that all of the analyzed parameters were within EPA's drinking water standards. Turbidity issues were also observed by the Department on September 15, 2008, with an apparent infiltration of sediment into the spring system. A substantial decrease in flow became apparent in the days following the initial turbidity problem. Based on this evidence, the Department has concluded that recent pipeline construction associated with oil and gas activity had caused your water supply to become contaminated with sediment. Actions taken by Seneca Resources appear to have rectified the problems with your spring, as on October 16, 2008 the quality and quantity of the water seem to be adequate for the purpose served by the supply.

Enclosed are the complete water sample analysis results from September 15, 2008 and a fact sheet to help you interpret the report. If you have any questions, or if any future issues arise, please contact me at 814-723-3273.

Sincerely,


Brian B. Ayers

Water Quality Specialist
Oil & Gas Management

Enclosures

cc: [REDACTED]

NWRO
WDO

BBA:rm

